



PURPOSE OF FLIGHT:

Nav. Cross Country No.8

TECHNICAL OFFICER'S REPORT:

Nil

ICA/PCL

MULT

~~ICM/POL-TAA~~ OK

NATURE OF ACCIDENT:

Anson II 11257 and Anson II 8480 collided while both a/c were apparently joining the circuit to land. Both a/c crashed to the ground, both pilots killed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2579

CAUSE:-

Mid-air collision. Contributory factors:- Failure of occupants of one or both aircraft to maintain a proper and careful lookout.

RECOMMENDATIONS:-

None.

CONCLUSIONS OF A.I.B.:-

Agree with findings.

CLASSIFICATION:

21. Collisions A/C

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: