

ACCIDENT CLASSIFICATION

UNIT 3 S.F.T.S. Calgary		COM. 2	PLACE M.A.			DATE 8-8-45	TIM 2350	
A/C TYPE HARVARD IIB		No. FH129	CRASH CAT. "D"		S.E. X	M.E.	DAY	NIGHT X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
GB	Houghin, A.D.B.	F/O	153785	P	Nil		No.	DATE
GB	Mortimer, N.K.	F/O	188537	PP	Nil		AL32	9-8
							D 14 (REVISED)	
							No.	CHECKED
							1	
							# 4	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Wasp 1340 AN1		42-10184/22576		ON TYPE		TOTAL		
		INST.	NIGHT	DUAL	SOLO	DUAL	SOLO	
		81	72	217	867	225	931	
		67	59	72	152	227	728	

COMMAND MONTH STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
CURT
3RD
5
M.F.

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instructor check out for night flying.

TECHNICAL OFFICER'S REPORT:

Nil

LU/PSU ✓

NATURE OF ACCIDENT:

Pilot undershot striking fence at
leeward boundary of field. No moon
5/10 middle and high clouds. Visibility
greater than 15 miles.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Undershot.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: