

ACCIDENT CLASSIFICATION

UNIT 124 Ferry Sqdn.		COM. 1 A.C.	PLACE Brantford, M.A. Brantford, Ont.		DATE 24-11-45	TIME 1530		
A/C TYPE HARVARD II			NO. AH185	CRASH CAT. "D"	S.E. X	M.E.	DAY X	NIGHT
PERSONNEL Crawford, H.H.		RANK F/O	NUMBER J47535	DUTY P	INJURIES Uninj.		SIGNAL NO. A969 DATE 1-12-45	
							D 14 (REVISED)	
							NO. CHECKED	
							#3	
ENGINE Wasp	ENGINE NUMBER (S) 4520/8759		HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE		TOTAL	
					DUAL	SOLO	DUAL	SOLO
			110	103	50	225	134	1872

COMMAND

MONTH

STAGE OF FLIGHT


- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ. 3rd
- INJURY 5

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Ferrying of A/C

TECHNICAL OFFICER'S REPORT:

TUC/UDL ✓
- U.C.

NATURE OF ACCIDENT:

Pilot claims after touchdown, that
after taxiing 200 yds, that stbd. oleo
leg collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

8. U/C Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: