

UNIT: (I.T.S.) #1SFTS
Camp Borden.

PLACE: Camp Borden, Ont.

DATE: 13-3-40

TIME: 1415 ✓

A/C

TYPE: Harvard N.A. 61 NUMBER: 1350

CRASH:

CATEGORY: C 7

H.Q. FILE NO: 1100-13-50

OCCUPANTS

FLYING TIME

NAME	RANK	NO.	CLASS	EXTENT OF INJURIES	INST	NIGHT	ON TYPE		TOTAL	
							DUAL	SOLO	DUAL	SOLO
McCann, D.S.	P/O(P)		P	Uninjured						

ACCIDENT CLASSIFICATION

SERIOUS

FATAL

INJURY

THIRD PARTIES: None

PARACHUTE DESCENT: no

AIRFRAME	DATE PURCHD	HOURS SINCE	LAST CPT E O'HAUL		EXTENT OF DAMAGE	REPORTS		
			DATE	HRS. SINCE		FORM	SERIAL NO.	DATE
Harvard 1350 ENGINE		358.30	N.A.		R. Wing panel and tips damaged	RCAF L3	2476	14-3-40
Wasp S3H1		376.20	N.A.		None internal Airscrew bent			

REFERENCE TO REPORTS

TELEGRAPHIC REPORTS:

SIGNAL NO: 214

DATE: 13-3-40

UNIT OR COMMAND: 1065 DATE: 13-3-40

UNIT OR COMMAND FILE NO DATE

P 2P PP FI WO AG AO OC Pass

DUTY ON WHICH ENGAGED: practice flying
3 training course.

NATURE OF ACCIDENT & STAGE OF FLIGHT:
Wing stall when attempting to land.

PRIMARY CAUSE: Error of judgment.,
Pilot misjudged height of aircraft
from ground.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
Weather and lack of experience.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

DATE:
COMPOSITION:

LH/PSHH

RECOMMENDATIONS:

ACTION TAKEN:

(a) Disciplinary (b) Technical (c) other

Recorded by _____ Date _____

Checked by _____ Date _____