

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT No. 2 S.P.T.S. Uplands, Ottawa.		COM. 3	PLACE Edwards Field				DATE 19-12-40		TIME 0920		H.Q. FILE		
A/C TYPE Harvard		No. 2689	CRASH CAT. C	SE X	ME	DAY X	NIGHT		MISCELLANEOUS CAUSES				
NAME		RANK	No.	DUTY	INJURIES				SERIOUS				
Hume, W.G.M.		F/O	C1629	P	Uninjured				FATAL	INJURY			
Croker, J.P.		LAC	916992	PP	Uninjured				CARD SERIAL No.				
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS						
Harvard		2689					INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.
Wasp							DUAL	SOLO	DUAL	SOLO			
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT	FILE		DATE				
270		19-12-40 T157		19-12-40									
NATURE OF ACCIDENT													

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

- TECH.
- DISOB.
- NEG WCE
- INEXP WCE
- MISCEL.
- INSTRUCT.
- FLT. CONTR.
- OTHERS
- PRIMARY
- FL. CONTR.
- MOV. SURFS.
- STAB. SURFS.
- W. STRUTS
- LAND. GEAR
- FLOATS
- FUSE OR HULL
- TAIL SKID OR W.
- ENGINE MOUNT.
- MISCEL.
- UND/TD
- PRIMARY
- FUEL SYS.
- COOL SYS.
- IGNIT. SYS.
- LUBIN SYS.
- ENG. STR.
- AIRSCREW A.
- ENG. CONTR.
- MISCEL.
- UND/TD
- PRIMARY

- UND/TD
- PRIMARY
- HANDQ.
- INSTS.
- WEATHER
- DRINKS.
- ALG SURF.
- OTHER
- UND/TD
- PRIMARY
- TAXING
- LANDING
- TAKE-OFF
- FLIGHT
- STABTY
- FATAL
- INJ.
- SIB.

- JU.
- 31
- 30
- 29
- 28
- 27
- 26
- 25
- 24
- 23
- 22
- 21
- 20
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1
- 32
- 31
- 30
- 29
- 28
- 27
- 26
- 25
- 24
- 23
- 22
- 21
- 20
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1
- 32
- 31
- 30
- 29
- 28
- 27
- 26
- 25
- 24
- 23
- 22
- 21
- 20
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1

DUTY ON WHICH ENGAGED:

Flying instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

LUC/PCDUF/UCDL

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Failure to lower undercarriage,
landed with undercarriage re-
tracted.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Pilot neglected to lower
undercarriage.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____