

CASPIR ARCHIVAL METADATA

Serial:	R9700 (formerly 9700)
Title:	Avro Anson Mk. I serial:R9700 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1941-May-20. Anson s/n R9700 (formerly 9700). This accident involved 3 people. Buckley J, Craig HC, Eberle PW
Keywords:	RCAFAnson ,R9700 (formerly 9700),5 AOS,5 Air Observer School,Wawanesa Manitoba,1941-May-20,Buckley,Craig,EberleRCAF L20
Created:	1941-05-20
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#R9700

DUTY ON WHICH ENGAGED:

PUPIL TRAINING

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AT 5000 FEET ALTITUDE THE STARBOARD MOTOR FAILED AS ITS TANK RAN DRY. THE INTERCONNECTOR VALVE WAS OPENED AND THE OTHER ENGINE FAILED AND THE PILOT HAD TO MAKE A FORCED LANDING IN A FARMER'S FIELD.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

INCOMPETENCE IN NOT KNOWING HOW TO FOLLOW OUT THE METHOD OF USING INTERCONNECTOR VALVE OF GAS TANK.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

DEFINITE INSTRUCTION ON THE USE OF THE INTERCONNECTOR VALVE HAVE BEEN ISSUED TO ALL PILOTS AT THIS SCHOOL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIR LOCK IN GAS LINE

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____