

/	
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Preparing for flight. Swinging	OR COMMANDING OFFICER'S REPORT
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
A misunderstanding between the pilo	
of the a/c and an airscrew swinger.	,
The evidence disclosed that the eng	ine
man peer reit on contact wifer the	PFG- RECOMMENDATIONS:
) ceding flight from which it would a that the negligence of the proper c	ppear )
drill by the milet T/O Weed was w	esponsible Nil
PRIMARY CAUSE: for the accident.	C
)	•
Misunderstanding or negligence on part of pilot and ground crew.	the
)	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other
	(A) Disciplinary (B) Technical (C) Other
, )	Further instruction is being given on the proper
	sequence for airscrew swinging.
,	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
) ACL Ford struck on the hand by air-	RECORDED BY DATE
) screw.	)
)	CHECKED BY DATE
))))))))))))))))))))))))))))))))))))))	