

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																																																																								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																																																																																								
TECH.		DISOB.		NEG'NCE		INEXP'NCE		MISCEL.		INSTRUCT.		FLT. CONTR.		OTHERS		PRIMARY		FL. CONTRS.		MOV. SURFS.		STAB SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UND'TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTRS.		MISCEL.		UND'TD		PRIMARY		HAND.O.		INSTS.		WEATHER		DRKNS.		AL'G SURF.		OTHER		UND'TD		PRIMARY		TAXYING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		3RD.		1A		RAF		2A		3A		3B		3C		3D		3E		3F		3G		3H		3I		3J		3K		3L		3M		3N		3O		3P		3Q		3R		3S		3T		3U		3V		3W		3X		3Y		3Z	
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																																																																									
CAUSES OF ACCIDENTS																																																																																																																																																							
UNIT T. & D. Rockcliffe.						COM. # 3		PLACE Test & Development Establishment Rockcliffe.										DATE 23-2-42				TIME 1750																																																																																																																																	
A/C TYPE Bolingbroke						No. 9144				CRASH CAT. D 1		SE		ME x		DAY x		NIGHT																																																																																																																																					
NAME						RANK		No.		DUTY		INJURIES						SERIOUS																																																																																																																																					
Nil.																		FATAL		INJURY																																																																																																																																			
																		CARD SERIAL No.																																																																																																																																					
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																																																																											
Bolingbroke 9144												INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.																																																																																																																																	
																DUAL		SOLO		DUAL		SOLO																																																																																																																																	
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																																																																																			
A505 24-2-42																																																																																																																																																							
NATURE OF ACCIDENT																																																																																																																																																							

Accident

TYPE OF ACCIDENT
 TYPE OF ENGINE
 CATEGORY
 TYPE OF ACCIDENT
 TYPE OF ENGINE
 CATEGORY
 TYPE OF ACCIDENT
 TYPE OF ENGINE
 CATEGORY

CAUSES

STAGE OF FLIGHT

UND'TD
 PRIMARY
 HAND.O.
 INSTS.
 WEATHER
 DRKNS.
 AL'G SURF.
 OTHER
 UND'TD
 PRIMARY
 TAXYING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.
 1A
 RAF
 2A
 3A
 3B
 3C
 3D
 3E
 3F
 3G
 3H
 3I
 3J
 3K
 3L
 3M
 3N
 3O
 3P
 3Q
 3R
 3S
 3T
 3U
 3V
 3W
 3X
 3Y
 3Z

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

A/C dropped through loose planking
over scale well in hangar floor.
Repairs to A/F stbd. wing, motor
panel, landing light & jettison tube.
Repairs to U/C, stbd, wheel faring
airscrews.

RECOMMENDATIONS:

PRIMARY CAUSE:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY DATE

CHECKED BY DATE