



DUTY ON WHICH ENGAGED:

A/C 5957 parked on tarmac engine running.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C on tarmac with engine running, ran forward, airman in cockpit failed to stop, A/C collided with Tiger Moth 5989.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

A/C not secured against forward movement.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE