

TYPE OF A/C										CAUSES OF ACCIDENTS										MISCELLANEOUS									
PILOT					OTHERS					AIRFRAME FAILURE					ENGINE FAILURE					HANDO.					PRIMARY				
UNIT 35 E.F.T.S. Neepawa										COM. 2					PLACE 3 miles East of Plumas					DATE 3-3-43 TIME 1910					H.Q. FILE 1100-12-35				
A/C TYPE Tiger Moth					NO. 1235					CRASH CAT. NIL					SE X		ME		DAY		NIGHT X		MISCELLANEOUS						
NAME					RANK		NO.		DUTY		INJURIES					SERIOUS													
Southgate, P.F.					Lgc.		1337625		PP		NIL.					FATAL		INJURY			MISCELLANEOUS								
forced landing.										CARD SERIAL No.										MISCELLANEOUS									
																									MISCELLANEOUS				
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS										STAGE OF FLIGHT							
Tiger Moth 1235 NIL.												INST.		NIGHT		ON TYPE			TOTAL			LAST 6 MOS.		STAGE OF FLIGHT					
G. Major 268824/85939 NIL.																DUAL SOLO			DUAL SOLO					STAGE OF FLIGHT					
SIGNAL No. & DATE					UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE				
NATURE OF ACCIDENT										MISCELLANEOUS										STAGE OF FLIGHT									

DUTY ON WHICH ENGAGED:

Solo map reading exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Pupil got lost and made a
successful forced landing.**

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

51. Lost.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor admonished.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Visibility deteriorated while pupil
was flying.**

47. Weather.

RECORDED BY

DATE

CHECKED BY

DATE