

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Taxiing.

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

**Airman taxied A/C from the hangar
to the parking line without authority
and struck pile of lumber.**

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

2. Hitting obstructions.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Airman placed on charge.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

17. Disobedience of standing orders.

RECORDED BY

DATE

CHECKED BY

DATE