

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE M.A.		DATE 23-11-43	TIME		
A/C TYPE HARVARD II B		No.	CRASH CAT. ND# 1 NFAA		S.E. X	M.E.	DAY	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Bennett, H.J.		F/O	137761	FI	Uninj.		NO.	DATE
Rossitter, A.		LAC	1582681	PP	Uninj.			
							D 14 (REVISED)	
							No.	CHECKED
							11-40	<input checked="" type="checkbox"/>
							#120	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp R.1340/ AN/1	42/1146/21070 NIL.		INST.	NIGHT	ON TYPE		TOTAL	
					SOLO	DUAL	SOLO	DUAL
			-	-	820	100	870	155
			-	-	62	85	99	117

N.A.F.A.

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

3rd
5
M

PURPOSE OF FLIGHT:

Bow Flying Cross Country.

NATURE OF ACCIDENT:

Damage to lower portion of rudder discovered on "between-flight" inspection.

TECHNICAL OFFICER'S REPORT: - Rudder damaged by striking some object from the side, probably whilst turning when taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

59. Obscure.

ACTION TAKEN:

NIL.