

CASPIR Aircraft Accident Cards

Serial: 10722

Title: Fairchild Cornell Mk. II serial:10722 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-17. Cornell II s/n 10722. This accident involved 3 people. Jackson C, Nelson MD, Wiglow AR

Keywords: RCAF Cornell II, 10722, 15 EFTS, 15 Elementary Flying Training School, Aerodrome, 1943-December-17, Jackson, Nelson, Wiglow RCAF L20

Created: 1943-12-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10722>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Starter would not turn engine so Pilot turned switches off and called switches off, tarmac crewman, A.R. Wiglow, then pulled propellor through to see if engine was too cold to start. Engine started and struck A.R. Wiglow on the hand. Pilot immediately re-checked switches off.

CLASSIFICATION:

~~56. Propellor swinging.~~ 24

24 Prop.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.