

DUTY ON WHICH ENGAGED: Formation flying landings and take-offs. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Landed with undercarriage retracted.	COURT OF INQUIRY, INVESTIGATING OFFICER LUC/PCDUF/UCDL OR COMMANDING OFFICER'S REPORT: COMMANDING OFFICER'S REPORT DATE: 13-2-41 COMPOSITION: \$/L N.E. KENNEDY	The state of the s
))))))) PRIMARY CAUSE: NEGLIGENCE. THE UNDERCARRIAGE HORN WAS CUT OUT DURING THE GLIDE DOWN. THE PILOT DID NOT BURST HIS ENGINE ON THE WAYS DOWN AS HE HAD BEEN INSTRUCTED TO DO AND AS A	RECOMMENDATIONS: DISCIPLINARY ACTION ACTION TAKEN: (A) DISCIPLINARY (D=Takenese (C) OTHER-	
CONSEQUENCE THE HORN CIRCUIT WAS NOT COM- PLETED SECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECORDED BY DATE	