

DUTY ON WHICH ENGAGED: Practicing landing.	COURT OF INQUIRY, INVESTIGATING OFFICER LBG/ATO/PSW  OR COMMANDING OFFICER'S REPORT:
	Commanding Officers Report.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 19-2-41
Landing On soft snow.	COMPOSITION:
	Group Captain (F.S. MGGill.)
PRIMARY CAUSE:  Wheels breaking through crust of deep snow on unrolled portion of field causing aircraft to turn	RECOMMENDATIONS: The provision of skis for one aircraft will solve the problem. In addition to the standard boundary markers, this Unit will in future use a number of cones (of dark coloured building paper) which will be used by the tractor operators to mark off the rolled portion of the aerodrome while that operation is still
over on its back.	ACTION TAKEN: in progress.  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
,	,
•	. )
•	)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Pilot being unable to distinguish between rolled and unrolled area	RECORDED BY DATE
of field.	·