

Τ))
^	DUTY ON WHICH ENGAGED: Formation flight.	COURT OF INQUIRY, INVESTIGATING OFFICER TLCOXCL)
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Struck tree in low lewel formation flying. During formation flying, formation went into a sugmedive. Harvard 2618 did not realize its actual height and aircraft struck a tree. No real damage was done so the aircraft was able to return back to the aerodrome.	OR COMMANDING OFFICER'S REPORT: INVESTIGATING OFFICERS REPORT. DATE: 4-3-41 COMPOSITION:)))
00000000	PRIMARY CAUSE: Error of judgment of leader in formation flightin that he led Harvard 2618 to fly into trees.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER WING COMMANDER E.A. MCNAB. STATES THAT IT IS HIS INTENTION TO ENDORSE THE PILOT'S LOG BOOK C.A.P. 200, SECTION 4, PARA. 25 (B).	
<u> </u>	SECONDARY CAUSE OR CONTRIBUTING FACTORS: LOW FLYING UNAUTHORIZED, BUT F/O RICHER UNDERSTOOD IT COULD BE DONE WITHOUT AUTHORIZATION IN AN OPERATIONAL SQUADRON.	N RECORDED BY DATE))
))) <u>)))))))))))))))))) </u>	O))))))))))))))))))))) (