

DUTY ON WHICH ENGAGED: COURT OF INQUIRY INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: General flying practice. Court of Induiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 14-2-41 COMPOSITION: Squadron LeaderG.D. Macallaster. Collision of aircraft in mid-air. LAC Nesbitt, pilot of 3357, while Flight Lieutenant P.A. Benedict climbing form below, and to the Flying Officer L.M. James. left of Yale 3370, struck the port wing RECOMMENDATIONS: A.M.T. states 1700-3357 d/27-2-41 of 3370 with that portion of the that no blame for this accident should be fuselage between the rear cockpit attached to LAC Wallace and he is to be enclosure and the vertical fin. Yale so informed. TRIMENIO 3357 went into a spin as a result of the collismon and the pilot abandoned the aircraft. The pilot struck the tail of his machine and **ACTION TAKEN:** failed to pull the rip cord soon (A) DISCIPLINARY (B) TECHNICAL (C) OTHER enough. He was fatally injured. Primary Cause: Probable attempt AMT approves D.6 24-2-41. on the part of LAC Nesbitt to Ilv formation with Yale 3370. SECONDARY CAUSE OR CONTRIBUTING FACTORS: RECORDED BY DATE CHECKED BY DATE