

	NATURE OF ACCIDENT AND STAGE OF FLIGHT:  overshot aerodrome and turned over in soft snow.	OR COMMANDING OFFICER'S REPORT:  Common Date:  COMPOSITION:	manding Officers Report. 3-41 up Captain H.E. Walker.
	PRIMARY CAUSE: Overshooting due to  inexperience. Pilot approaching to hight and too fast.  The pupil had received duel instructions, and carried out solo landings with flaps up on two previous accasions. It is considered that the accident was due to inexperience and error of judgment. It is not proposed to take disciplinary action other than an interview with his Squadron ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  COMMENDATIONS:  The pupil had received duel instructions, and carried out solo landings with flaps up on two previous accasions. It is considered that the accident was due to inexperience and error of judgment. It is not proposed to take disciplinary action other than an interview with his Squadron Commander.		
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		-
·)	Aircraft over running the boundary of the Aerodrome, and turning over in the soft snow.		RECORDED BY DATE