

1)))))))))))))))))))))	3 3 3 3 3))))))	10
)	DUTY ON WHICH ENGAGED:	OR COMMANDING OFFICER'S REPORT.			
)	Flying Practice.	THE OWNER OF THE OWNER OWNER.		- PISTPENTE TESTEMIL	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	Commanding Of 30-3-41	fficers Report.	-
))))	Aircraft Nosed Over Damaging airscrew . After pilet emerged from clouds, he noticed a river on his right and mistock it for the Ottawa River. After looking for a pinpoint on this river his	RECOMMENDATIONS:	Group Captain F.S. McGill.		
))	fuel became low, thus necessitating PRIMARY CAUSE: a forced landing.	E			din
)))	Error in judgment on the part of the pilot due to inexperience in that he became lost and was forced to ACTION TAKEN: land at an only partially serviceable (A) DISCIPLINARY (B) TECHNICAL (C) OTHER airport.				
; }	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft striking slush on landing.			30141	
) }				RECORDED BY DATE	ر. د
)))))))))))))))	<u> </u>)))))	CHECKED BY DATE	
1					