

```
LH/PSHD/USD/WWG
DUTY ON WHICH ENGAGED:
                                       COURT OF INQUIRY, INVESTIGATING OFFICER
                                       OR COMMANDING OFFICER'S REPORT:
 Take-offs and landings, medium turns.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                       DATE:
                                       COMPOSITION:
 Ground looped after landing. The
 pupil counteracted for drift by
 keeping right wing down. He levelled
 off just prior to touching down and BECOMMENDATIONS:
 as he brought the aircraft's control
 column back it drifted slightly to
 the left. As the wheels touched, the
         Faircraft wwwng to the right
and he applied full left rudder but the
aircraft continued to swing. It then
 skidded sideways in 5 or 4 bounces ACTION TAKEN:
and the undercattiage collapsed.
                                         (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Primary Cause: Failure of the pupil
to counteract the drift sufficiently
before landing and failure to apply
sufficinet corrective measures due
SECONDARY CAUSE OR CONTRIBUTING FACTORS:/to
                     inexperience.
The incoming wind was gusty at
                                                                     RECORDED BY
                                                                                         DATE
30 degrees across the runway from
the right.
                                                                     CHECKED BY
                                                                                         DATE
```