

PILOT OTHERS		AIRFRAME FAILURE ENGINE FAILURE		CAUSES OF ACCIDENTS		DATE TIME		19-4-41 15:00		HAND Q.	
UNIT # 33 S.F.T.S. CARBERRY MANITOBA		COM. 2		PLACE 12 WEST OF CARBERRY # 33 S.F.T.S.		H.Q. FILE				PRIMARY	
A/C TYPE HARVARD		No. 2924		CRASH CAT. A		SE X		ME ME		DAY NIGHT X	
NAME GILES J.H. CAMP J.H.		RANK LAC LAC		No. 1257946 1170004		DUTY PP PP		INJURIES KILLED KILLED		SERIOUS FATAL INJURY 2	
TYPE A/F & ENGINE HARVARD WASP 33H1		No. 2924 8695/4456		EXTENT OF DAMAGE TOTAL TOTAL		REPORT FORM SERIAL No. DATE		HOURS FLOWN BY PILOTS INST. NIGHT ON TYPE DUAL SOLO		TOTAL DUAL SOLO LAST 6 MOS. 97	
SIGNAL No. & DATE		UNIT No. & DATE		COM. No & DATE		REPORT		FILE		DATE	
NATURE OF ACCIDENT											

DUTY ON WHICH ENGAGED:

INSTRUMENT FLYING.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AIRCRAFT STALLED ON TURN.

PRIMARY CAUSE:

DISOBEYING REGULATIONS AND CARRYING OUT
UNAUTHORIZED LOW FLYING.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT STALLED ON TURN.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

ZLOC/AOC/POL/ACDM ✓

COURT OF INQUIRY

DATE:

COMPOSITION:

President: S/Leader R.N. Dupont

Members : F/Officer J.P. Meadow

P/Officer J.F. Nolman

RECOMMENDATIONS:

F/Officer E.W.C. Sharpe.

In Attendance: F/Officer

ALL PUPILS AGAIN WARNED AGAINST DISOBEDIENCE
OF REGULATIONS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____