

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	LM/WWG
CROSS COUNTRY.	OR COMMANDING OFFICER'S REPORT:	TWI VA AAO
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: MONTHLY ACCIDENT	RETURN.
AFTER LANDING IN CROSS WIND, THE WIND LIFTED	COMPOSITION:	
THE PORT WING CAUSING STARBOARD WING TO TOUCH		
GROUND. AIRCRAFT SHUNG AND GROUND LOOPED.		
	RECOMMENDATIONS:	
	•	
PRIMARY CAUSE:		• •
INEXPERIENCE ON THE MART OF THE PILOT.		
INCAPCATION OF THE PICOL		
	ACTION TAKEN:	•
	(A) Disciplinary (B) Technical (C) Other	ER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
FAILURE OF PILOT TO ALLOW FOR WIND.		
	REG	CORDED BY DATE
	сн	ECKED BY DATE