

DUTY ON WHICH ENGAGED:

Circuits and landings

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

LHC/ANT/UTB

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Heavy landing on runway bursting
port tyre air craft swung off runway
damaging both airscrews.

RECOMMENDATIONS:

Pilot interviewed and extension of runway
and levelling of drainage channel
urgently requested.

PRIMARY CAUSE:

Port tyre burst

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Narrowness of runway.

RECORDED BY

DATE

CHECKED BY

DATE