

DUTY ON WHICH ENGAGED:

Routine training flight

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft forced landed on aerodrome.
Failing of starboard engine (broken
connecting rod) Pupil flew back on
one engine and made successful
landing on aerodrome.

PRIMARY CAUSE:

Broken connecting rod.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

Monthly Accident Return.

COMPOSITION:

SFE/ET/IM/D/E

RECOMMENDATIONS:

Adequate orders have now been issued
to prevent recurrence of this type
of accident.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY

DATE

CHECKED BY

DATE