

)))))))))))))))))))))))))))))))))))))) 	50
)	DUTY ON WHICH ENGAGED: " CIRCUITS AIRDROME LANDING AT NIGHT.	OR COMMANDING OFFICER'S REPORT: 25/255)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: Monthly Accident Return. COMPOSITION:)
Ó	AIRCRAFT GROUND LOOPED AFTER LANDING. THE PILOT HAD MADE A LANDING AND WAS RUNNING ON ALL THREE WHEELS, WHEN SUDDENLY THE A/C	COMPOSITION:)
)	SWUNG VIOLENTLY TO THE RIGHT. PILOT ATTEMPTED TO STOP SHING BY APPLYING FULL LEFT RUDDER AND	RECOMMENDATIONS:)
))	PRIMARY CAUSE:		5]
)	INEXPERIENCE ON THE PART OF THE PILOT. FAILURE OF THE PILOT TO ATTEMPT TO CORRECT		ာ ၁
)	SWING SOON ENOUGH DUE TO INEXPERIENCE AT NIGHT.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
))
·)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
))	Ground loop	RECORDED BY DATE	_)
<u>ز</u>		CHECKED BY DATE	_)
<u> </u>	, , , , , , , , , , , , , , ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ָנִ נ