

/:))	DUTY ON WHICH ENGAGED: Flying Training.	COURT OF INCHIBY	INVESTIGATING SEE		3 3 3 S)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Landing with undercarriage retracted WHILE INSTRUCTING ON INSTRUMENT TAKE-OFF AND CIRCUITS, THE PILOT NEGLECTED TO LOWER THE U/C	DATE:	FORTY EIGHT HOUR 6-6-41 GROUP CAPTAIN W.	REPORT.)
<i>)</i>	OF THE VC RESULTING IN A WHEELS UP LANDING. RECOMMENDATIONS:)
)	PRIMARY CAUSE: Entry made in pilot s log book to the effect that Cause of accident was assessed as gross carelessness.					\overline{c}
))	Carelessness. on the part of the pilot.)
))	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other)
)				•	÷ŧ)。)。
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	;	•)
)	AIRCRAFT LANDED WITH U/C RETRACTED.			RECORDED BY	DATE) i
)) :		· • • • • • • • • • • • • • • • • • • •))))))	CHECKED BY)) DATE)