

DUTY ON WHICH ENGAGED:

Dual instruction.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft ground looped on landing.
Officer instructor with pupil in
a/c 3020 swung on the runway after
landing, and was not able to correct
this in time to prevent the a/c
from ground looping, damaging the
aircraft.

PRIMARY CAUSE:

Pilot's error.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

LS/PSS ✓
Monthly Accident Return.

DATE:

COMPOSITION:

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft swung off the runway upon
coming into land.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____