

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		J
DUTY ON WHICH ENGAGED: LANDING	COURT OF INQUIRY, INVESTIGATING OFFICER	
-vuning	OR COMMANDING OFFICER'S REPORT: LH/PSHH/IJUSH	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: Monthly Accident Return.	
IN LANDING AIRCRAFT DROPPED HEAVILY ON GROUND		
	RECOMMENDATIONS:	
	RECOMMERDATIONS:	
•		
PRIMARY CAUSE:		
PUPIL FILOT PULLEDRITHE CONTROL COLUMN BACK		
SUDDENLY TO CORRECT AIRSPEED ON LANDING WHICH CAUSED AIRCRAFT TO ZOOM UPWARDS.		
INSTRUCTOR PUSHED THE NOSE DOWN AND OPENED TH	THEACTION TAKEN:	
THROTTLE. THE AIRCRAFT WAS FALLING RAPIDLY	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
AND THE ENGINE DID NOT PICK UP UNTIL AFTER		
THE AIRCRAFT HIT THE GROUND		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Instructor's failure to correct hi	<u> </u>	
pupil's error in time to prevent accident	RECORDED BY DATE	•
was a second of the second of		_
	CHECKED BY DATE	_