



DUTY ON WHICH ENGAGED:

**Aircraft Test.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Port engine failed after take off when at approx. 300'. Aircraft would not maintain height on one engine and made successful forced landing. Aircraft undamaged.**

DATE:

**Monthly Accident Return.**

COMPOSITION:

**O/M/R/O/P/E/S/NK/NK/O**

RECOMMENDATIONS:

PRIMARY CAUSE:

**Pilot forced landed when engine failed after take-off.**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Aircraft would not maintain height on one engine.**

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_