



DUTY ON WHICH ENGAGED: 0007.

Cross country exercise.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil returning to base encountered severe thunderstorm. Executed precautionary landing; aircraft ran approximately two hundred and fifty yards, struck soft patch and overturned.

PRIMARY CAUSE:

Aircraft striking soft patch during landing run.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Overturning due to wheels sinking in soft portion of field.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

Monthly Accident Return.

COMPOSITION:

FM/LNVE

RECOMMENDATIONS:

Pupils again warned not to enter thunderstorm at any time. Go back to clear weather or if local ground it.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY

DATE

CHECKED BY

DATE