

CASPIR Aircraft Accident Cards

Serial: 6598

Title: Avro Anson Mk. I serial:6598 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1941-July-28. They are: Anson s/n 2210 (assigned to 6598), Anson s/n 6598. This accident involved 1 person. Teask GR

Keywords: RCAFAnson ,6598,15 EFTS,15 Elementary Flying Training School,Aerodrome,1941-July-28,TeaskRCAF L20

Created: 1941-07-28

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6598>

DUTY ON WHICH ENGAGED:

TAKE OFFS AND LANDINGS

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

STARBOARD WHEEL RETRACTED WHILE
TAXIING

PRIMARY CAUSE:

INCORRECT COCKPIT PROCEDURE

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

TUC/PEDUW/UCDT

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Failure of the pilot to properly un-
dercarriage retraction and locking
device prior to landing.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____