

CATEGORY	TYPE OF ENGINE	TYPE OF A/C	CAUSES OF ACCIDENTS										MISCELLANEOUS CAUSES	STAGE OF FLIGHT			
			PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE						
			UNIT 12 S.F.T.S. BRANDON, MAN		COM. No. 2	PLACE AERODROME				DATE 2-7-41	TIME 1000						
			A/C TYPE CRANE		No. 7742	CRASH CAT. C 14		SE	ME X	DAY X	NIGHT						
			NAME		RANK	No.	DUTY		INJURIES			SERIOUS					
			ROBERTSON, J.A.		SGT	R63673	FI		UNINJURED			FATAL	INJURY				
			MACE, A.L.		RNZAF	LAC	405300		PP			UNINJURED					
			TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE		HOURS FLOWN BY PILOTS						
			CRANE		7742	SERIOUS					INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.
			JACOBS		4023/21167	NIL							DUAL	SOLO	DUAL	SOLO	
			JACOBS		4023/21168	NIL									21		
			SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT	FILE	DATE						
			CT 3		2-7-41												
			NATURE OF ACCIDENT														

DUTY ON WHICH ENGAGED:

FLYING INSTRUCTION

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AIRCRAFT OVERSHOT IN LANDING IN ATTEMPT
TO AVOID PILE OF EARTH THROWN UP BY
CONTRACTORS AND OVERTURNED

DATE:

COMPOSITION:

10/P50

RECOMMENDATIONS:

NIL

PRIMARY CAUSE:

PILOT OVER SHOT ON LANDING

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

UNDERCARRIAGE GAVE WAY IN SWERVE TO
AVOID MOUND OF EARTH

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____