

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
PILOT		OTHERS		AIRFRAME FAILURE														ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																					
UNIT 17 E.F.T.S. STANLEY, N.S.		COM. No. 3		PLACE AERODROME														DATE 19-7-41		TIME 1200																	
A/C TYPE FINCH		No. 4786		CRASH CAT. C 14		SE X		ME		DAY X		NIGHT		H.Q. FILE 1100-47-86																							
NAME				RANK		No.		DUTY		INJURIES										SERIOUS																	
BRIGHT, D.A.								FI		UNINJURED										FATAL																	
LAZIER, C.S.				LAC		R88673		PP		UNINJURED										INJURY																	
<i>No record</i>																				CARD SERIAL NO.																	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																									
FINCH II		4786		SLIGHTLY								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																			
KINNER B5R		6410		SLIGHT																																	
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																							
T 62		19-7-41																																			
NATURE OF ACCIDENT																																					
MISCELLANEOUS CAUSES																																					
STAGE OF FLIGHT																																					

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

DUAL INSTRUCTION

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: R.170

INSTRUCTOR TAXIED AIRCRAFT INTO STEAM
ROLLER WHICH WAS PARKED ON RUNWAY AND NOT
MARKED BY RED FLAG

COMPOSITION:

TCO/PC7/XOV

RECOMMENDATIONS:

PRIMARY CAUSE:

STRUCK STEAMROLLER WHILE TAXIING ON RUNWAY

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot reprimanded, construction Co.
warned to keep proper signals on
equipment & not to leave them on
runways. Endorsement of Pilot's Log-
Book.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

No red flag on steam roller.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____