

CASPIR Aircraft Accident Cards

Serial: AJ950

Title: North American Harvard Mk. II / 2 serial:AJ950 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-February-21. They are: Harvard II s/n FE283, Harvard II s/n AJ950. This accident involved 2 people. Pritchard CJ, Statters E

Keywords: RAFHarvard II,AJ950,41 SFTS,41 Service Flying Training School,Aerodrome,1943-February-21,Pritchard,StattersRCAF L20

Created: 1943-02-21

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ950>

DUTY ON WHICH ENGAGED:

Solo formation.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While in formation pitot head of FE283 came into contact with port elevator of AJ950. Both A/C returned to base and made successful Landings.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

26. Collision in the air.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Error in Judgment".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Error of judgment by pilot of FE283.

RECORDED BY

DATE

CHECKED BY

DATE