



DUTY ON WHICH ENGAGED:

Night flying circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C 2654 skidded into rudder of AJ924.

DATE:

D-14

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

3. Hitting other A/C.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER  
Pupil grounded for one month.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Light blown snow from A/C which took off in front of A/C 2654.

RECORDED BY

DATE

CHECKED BY

DATE