

DUTY ON WHICH ENGAGED:

Taxiing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Proceeding to take off Harvard
2810 taxied into Harvard 3035
which was lined up for take-off.

DATE:

COMPOSITION:



RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's log book endorsed "Gross Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Carelessness on part of pilot of
Harvard 2810 in that he failed
to keep a sharp look out.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____