



DUTY ON WHICH ENGAGED:

Taking off.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C force landed immediately after take-off, landing carried out with wheels down in very rough field.

DATE: 26 Feb./43

COMPOSITION:

INVESTIGATING OFFICER

F.O. K.H. MacKay (J9263), #6 SFTB. ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54 Engine failure in the air.~~

~~47. Weather. Icing on mainplanes and tailplanes.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*13 Force Land!*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_