

CASPIR Aircraft Accident Cards

Serial: 7427

Title: Avro Anson Mk. II serial:7427 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-February-06. Anson II s/n 7427. This accident involved 3 people. Fletcher TE, Jenkinson GH, Price DA

Keywords: RCAFAnson II,7427,8 BGS,8 Bomb & Gunnery School,Aerodrome,1943-February-06,Fletcher,Jenkinson,PriceRCAF L20

Created: 1943-02-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7427>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Routine bombing night exercise.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot landed with u/c retracted.

COMPOSITION:

D-14 ✓
LVC/PCDUF/USDL

RECOMMENDATIONS:

Adherence by pilots to correct cockpit procedure and check at all times.

PRIMARY CAUSE:

~~34. Wheels up landing.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot reprimanded, Log book endorsed and appropriate logging form made out.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot neglected to carry out the correct cockpit check and procedure on his down wind leg prior to asking and receiving permission to land.~~

u/c Drill - in air

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____