

101018

CF101B

57-306


RCAF REGISTRATION NUMBER

TYPE

MARK

RECORD OF TRANSFERS

DATE	AUTHORITY	ALLOTTED TO	REMARKS
30 June 70	QTO 253	11E from USRF C-119 on Project - Peace Wings	
30 June 70	QTO 253	401CFTSD	Business via LCI & ^{dep to 254 20 May 71} Argonneville
30 June 70	QTO 253	GAC-425 AW (F) Sp. 12/20	Business wing TSD LOG 4670 See 271520 19 May 71 Unit Change
30 June 70	QTO 253	GAC-416 AW (F) Sp. 12/20	Business wing TSD LOG 4670 See 271520 19 May 71 Unit Change
31 Aug 71	RBC QTO 29	GAC-409 AW (F) Sp. 12/20	Business wing TSD LOG 4670 See 271520 19 May 71 Unit Change read at 6th hour 1 Sep 71



101018

CF101B - SINGLE

J57-P-55

USAF No. 57-306

"A" Crash Lost at sea 29 Nov 79 engine

630293-631732

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

Wpg from USAF in Exchange

INITIAL ENTRY AT Bristol Aerospace Ltd

DATE 30 Jun 70

QTO No.

QT0253

Project

CD No. Peace Wings

TRANSFERS

1510-21-804-5152

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
30 Jun 70	QT0253	630704 609505 Bristol Aerospace Ltd	24 Mar 75	QT016	AG CFB Beamor
30 Jun 70	QT0253	ADC 425 AW(F) Son Beville via ITV Greenville 416 (1 Sept 71) Chatham	24 Mar 75	QT016	CT 409 Ldn Beamor
departed 29 Nov 79	(627671, 629035)		25 Oct 77	QT0231	Lt Btl w/sg 1632251 632042
31 Aug 71	ADC QT029	ADC-409 AW(F) Sp. Comoy 632374 633796	25 Oct 77	QT0231	CT 409 Ldn Beamor 632251 632042
19 Mar 73	QT0475	Btl w/sg (629047, 627878) 632152 632138	24 Mar 75	QT016	AG CFB Beamor
19 Mar 73	QT0475	ADC 409 AW(F) Ldn Beamor	24 Mar 75	QT016	CT 409 Ldn Beamor
24 Mar 75	ADC QT016	AG CFB Beamor	7 Jan 80	QT0327	KX CFB Beamor 631732 630293
24 Mar 75	ADC QT016	CT 409 Ldn Beamor	20 Feb 80	QT0355	Strike off
24 Mar 75	ADC QT016	AG CFB Beamor			
24 Mar 75	ADC QT016	CT 409 Ldn Beamor			
23 Mar 76	QT0374	Lt Btl w/sg {632534, 632528}			
23 Mar 76	QT0374	ADC 409 Ldn Beamor {633977, 609527}			

OVERHAUL DATA

DATE	QTO NO.	CONTRACTOR		REPAIRS
30 Jun 70	QTO253	BAL	.CD2790813	Project Peace Wings Exchange Work and to ADC
via LTV Greenville for FCS testing, MB5 Mod installation and painting.				
19 Mar 73	QTO475	BAL	2794801	DLIR
23 Mar 76	Q10374	BAL	2795801	DLIR
25 Oct 77	QTO231	BAL	2796801	Fuel cell replacement