

101057

CF101B - SINGLE

J57-P-55

USAF No. 57-429

1510-21-804-5152

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

Wpg from USAF in Exchange

INITIAL ENTRY AT Bristol Aerospace Ltd

DATE 30 Jun 70

QTO No.

QT0253

Project
CD No. Peace Wings

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
30 Jun 70	QT0253	629816, 631839 Bristol Aerospace Ltd	9-3-81	QT0304	626982-632543 EX 409 Comox
30 Jun 70	QT0253	ADC 409 sqn ^{151st} Comox via ITV Greenville	19-4-82	QT0114	LX 401 BAL ⁶³⁰⁹⁸⁰ 632536
632379 & 627609	replaced 9 burst	632374 627609	19-4-82	QT0114	EX 409 Comox ⁶³²³²² ↓
18 Mar 74	QT0503	LX BAL 409 ⁶³²⁵³⁵ 632638	19-5-83	QT0132	LX 401 BAL ⁶³²³²² 632529
18 Mar 74	QT0503	EX ADC ^{633577, 632535} 409 sqn ⁶³²⁶³⁸ via AWK ⁶³²⁶³⁸	19-5-83	QT0132	EX 409 Comox ⁶³²³²² ↓
17 Mar 75	QT0437	AG CFB Baginville	17-3-83	QT0350	LX 401 BAL ⁶³²³²² 632529
17 Mar 75	QT0437	EX AG 409 sqn Baginville	17-3-83	QT0350	EX 409 Comox ⁶³²³²² ↓
9 Mar 78	QT0320	LX 401 BAL 101057	12-7-84	QT0190	EX CFB Comox
9 Mar 78	QT0320	EX ^{409 Comox 628070} Baginville ⁶³³⁷⁹⁶	Strike off as a permanent display		
24 Mar 75	QT016 (ADC)	AG CFB Comox	monument		
24 Mar 75	QT016 (ADC)	EX 469 Sqn Comox			
9-3-81	QT0304	LX 401 BAL ⁶²⁶⁹⁸² 632543			

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
30-Jun 70	QTO253	BAL .CD2790813	Project Peace Wings Exchange Work and to ADC via ITV Greenville for FCS testing, MB5 Mod installation and painting.
18 mar 74	QTO 503	BAL CDW 2793801	D L R
14-8-81	DPSUP5532098	CDW 2790748	repair to fuselage formed Brackets
9-3-81	QTO 304	LX 401 BAL 2790748	for stabilator fly in exchange & 2790801 DPSUP5532124 23 Sep 81 repair
9-4-82	QTO 114	LX 401 BAL 2791801	for major periodic inspection
19-5-83	QTO 132	LX 401 BAL 2792801	fly in repair
17-3-83	QTO 350	LX 401 BAL 2792801	major periodic inspection