

101061

CF101B

57-434


RCAF REGISTRATION NUMBER

TYPE

MARK

RECORD OF TRANSFERS

| DATE | AUTHORITY | 1E for USAF ALLOTTED TO | REMARKS |
|------------|---------------|------------------------------|----------------------------|
| 30 June 70 | Q TO 253 | Co on Project - Peace Wings | |
| 30 June 70 | Q TO 253 | 411 CFTSD Briscoe via LTR | dep for Greenville 23/6/71 |
| 30 June 70 | Q TO 253 | RAC - 416 AW (F) San Chatham | red this do 12 Oct. 71 |
| 7 Oct 71 | RAC - Q TO 34 | RAC - 409 AW (F) Agur Comrod | red 5 Oct. 71 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |



101061

CF101B - SINGLE

J57-P-55

USAF No. 57-434

A'crash 5 Jul 76 (crash in sea)

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT Bristol Aerospace Ltd DATE 30 Jun 70

QTO No. QT0253

Wings
CD No. Project Peace

TRANSFERS

TRANSFERS

| DATE | QTO No. | TO | DATE | QTO No. | TO |
|--------------------|-----------------|--|-----------|-----------|--|
| 30 Jun 70 | QT0253 | 630275, 630031 Bristol Aerospace Ltd | 24 Mar 75 | ADC Q1016 | AG CFB Comox |
| 30 Jun 70 | QT0253 | ADC-416 AW (E) ^{Spaldham} via ITV Greenville | 24 Mar 75 | ADC Q1016 | CX 409 ^{631312, 632134} Comox |
| defected 23 Jun 71 | 632042 + 630295 | (Red chalk) 632535, 630307 | 7 Jul 76 | Q10160 | Rx CFB ⁶³²¹³⁴ Comox |
| 7 Oct 71 | ADC Q1034 | 632525, 630307 ADC-409 AW (E) ^{Sp Comox} | 19 Jan 71 | Q10293 | Strike off 'A'crash |
| 2 Oct 72 | Q10296 | 629047, 630293 Bristol Aerospace Ltd ^{refg} | | | 631312 ↓ 632134 |
| 2 Oct 72 | Q10296 | 629047, 630293 ADC 409 AW (E) ^{Sp Comox} | | | |
| 19 Mar 73 | Q10475 | Lt BAF ^{refg} / 630293 | | | |
| 19 Mar 73 | Q10475 | 632525, 630137 ADC 409 AW (E) ^{Sp Comox} | | | |
| 24 Mar 75 | ADC Q1016 | AG CFB Comox | | | |
| 24 Mar 75 | ADC Q1016 | CX 409 ^{Sp Comox} | | | |
| 24 Mar 75 | ADC Q1016 | AG CFB Comox | | | |
| 24 Mar 75 | ADC Q1016 | CX 409 ^{Sp Comox} | | | |

OVERHAUL DATA

| DATE | QTO No. | CONTRACTOR | | REPAIRS |
|-----------|---------|------------|-----------|---|
| 30 Jun 70 | QTC253 | BAL | CD2790813 | Project Peace Wings Exchange Work and to ADC VIA LTV Greenville for FCS testing, MB5 installation and painting. |
| 2 Oct 72 | Q10296 | BAL | 2791801 | Flyin repairs as reqd to install action enclosure |
| 19 Mar 73 | Q70475 | BAL | 2791801 | 40 LIR |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |