

21352

T33 PT

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURER'S No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
21 Sep 79	QT0237	duy glo painting project	547103A				
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	AIRCRAFT TYPE	NUMBER	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

MAJOR EQUIPMENT RECORD CARD

REMARKS

14-12-84 QT0317 2x402 MW8 for DLIR 2792832

(21352)
133352

T33 MK3 PT NENE 10

2

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

10 TSU (Contract)

DATE

8 June 54

QTO No.

1202

CD No.

511663

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
8 June 54	QTO-1202	+ C	30 Dec 65	QTO 670	TC 1 FTS Gimli (1815)
5 Oct 56	QTO 467	10 TSU NW 2 CR	25 Sep 69	QTO 355	Northwest Electric Education 1818
5 Oct 56	QTO 467	TC 100 Gimli	30 Dec 69	QTO 479	TC 1 FTS Gimli
10 June 59	QTO 324	10 TSU NW 2 CR	30 Jul 70	ALYH DURE-2	effective 22 Jul 70 + C 1 BFFTS Gimli (1203)
10 June 59	QTO 324	TC 2 AFS Gimli	20 Nov 70	QTO 433	WRANDU Director W-4118
28 Feb 61	1037	DRX-1000 Park	4 Feb 71	QTO 508	SR 1000 out of use (1203)
3 Jul 61	350	10 TSU NW 2 CR	27 May 71	QTO 162	TC 1 BFFTS Gimli (1203) CFB Cold Lake
9 Feb 62	929	DR 1000 Park MacDonald	1 Sep 71	CF 05-44-4	TC 1 BFFTS Cold Lake (22/7/71)
13 Apr 62	101	TC 100 Gimli	20 Sep 73	QTO 300	LT NW 2 Edmonton (1928)
20 Sep 63	TC QTO 17	TC - 2 AFS Portage	20 Sep 73	QTO 300	BY 1 CFFTS Cold Lake (1928)
31 Aug 64	TC QTO 31	TC FTS/AFS Moose Jaw	17 June 74	QTO 192	LT NW 2 Edmonton (1929)
2 Sep 65	QTO 439	10 TSU NW 2 Edmonton	8 Jan 75	QTO 353	BY VU32 Sherwood (1928)

7RC502

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
5 Oct 56	467	NW 9 572870	for CAIR
10 June 59	324	NW 9 772822	for necessary repairs to correct unapproved flying characteristics
3 Jul 61	350	NW 0 079833	CAIR ED 05-50C-7B.
2 Sep 65	439	NW 0 479833	CAIR ED 05-50C-7B
20 Sep 69	355	NW 0 879833	DLIR
20 Nov 70	433	WPA 400 WUNA - NSI	
20 Sep 73	300	NW 0 0792633	Staffing + refueling
17 June 74	192	NW 0 2793633	DLIR, WPA 400, damaged altimeter, 50011 diameter, do not heat med
29 Oct 79	272	LX AMDU Jinton Project E 74103A	for painting Wing Str 0 mod done at same time
17-11-81	QTO 270	LX AMDU Jinton	Commiss to carry out referenced Project WIA P13

12/4/89 QTO 708 LX NW 2. for over 6000 hours of flight. 20340 8467. 8- EA 61/01
 Time Cared 1147 hrs 50 min
 A/R allocated NW 9 5 Oct 56

DAM4420257 101010Z NOV 70 - AUTHORIZES NEW REGISTRATION NUMBER.

133352^A Crash T33 MK3 PT

NENE 10.

FAA REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT 1510-21-800-0508

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
14 Nov 78	232	LX NW I (1963)	14-12-84	QTO 317	LX 402 NW 2
10 Jan 79	267	CX VU 32 Shearwater ¹⁹⁶³	14-12-84	QTO 317	CX VU 32 Swater ¹³⁰⁸
21 Sep 79	237	LX AMDU Juntow	15-12-86	QTO 316	LX 402 NW 2 1308
21 Sep 79	237	CX VU 32 Shearwater^{9 Oct 79}	15-12-86	QTO 316	CX VU 32 Swater 1308
29 Oct 79	QTO 272	LX AMDU Juntow 1963	12/4/89	QTO 108	LX NW 2 1832
29 Oct 79	QTO 272	CX VU 32 Shearwater	12/4/89	QTO 108	CX 32 Swater 1784
29 Oct 79	QTO 274	LX AMDU Juntow ¹⁹⁶³	29/10/91	QTO 271	KX Swater 1927
30 Oct 79	QTO 276	CX VU 32 Shearwater 1963	10/4/92	QTO 109	Strike off 1927
17 Nov 81	QTO 270	LX AMDU Juntow 1963			
17 Nov 81	QTO 270	CX VU 32 Shearwater ¹⁹⁶³			
22-8-83	QTO 210	LX 402 NW 2 1927			
22-8-83	QTO 210	CX 32 Shearwater ↓			

