

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1.10.42	Time exp.	MacDonald Bro.					
13.10.42	Time exp	Aircraft Repair				Nov. 43	#470 SR.
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
9.1.42	C1"	MacLeod Aerod.	1045	TSFB 575	10/11	Lieut. R. Redell	-		
13.6.42		MacLeod Aerod	0815	TSBSS T39	13/6	Lieut. O.E. Olsen			
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

*Re. acc. 2. Eng. inst. 31687/30512. Loose earthing wire on starting magnets. Lieut. Gorrie severely injured.*

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>MacDonald Bros. Winnipeg</i>	DATE <i>28/1/41</i>	TRANSFER ORDER No. <i>5950</i>
--	---------------------	--------------------------------

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>8/2/41</i>	<i>#4 Training Command</i>	<i>T.O. 6084</i>			
<i>1/10/42</i>	<i>MacDonald Bros</i>	<i>T.O. 7602</i>			
<i>13.10.42</i>	<i>a/c Repair, Edmonton</i>	<i>T.O. F665</i>			
<i>16.1.43</i>	<i>Stored Reserve #47C 19/3</i>	<i>T.O. 4990</i>			
<i>25.3</i>	<i>#4 T.C. (#2 AOS) 1/4</i>	<i>T.O. 6427</i>			
<i>1.11.44</i>	<i>Apdal # 47C</i>	<i>T.O. 16922</i>			
<i>1/12/44</i>	<i>APDAL No. 2 A.C.</i>	<i>T.O. 17328(22)</i>			
<i>14.2.45</i>	<i>War Assets Corp.</i>	<i>T.O. 18548</i>			
	<b>DEC. SER NO G.R</b>	<b>2-23</b>			

REMARKS 28/1/41 -- INITIAL ENTRY - MACDONALD BROS., WINNIPEG T.O. 5960  
 + WINTER CONVERSION SET INSTALLED DURING ASSEMBLY. REF. LETTER FROM #15 T.O. 12/7/41, FILE 1021-22-1.  
*Mrs since new: 2533.40 U.K. Cont.*  
*Mrs since O' haul 1069.30*  
*Location. Swift current.*

ENGINE TYPE	CHEETAH IX	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	TP 223	LEDGER FOLIO	1200-38-9	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL		YEAR	TYPE	MANUFACTURERS No.		
			1941	T E TRAINER	W 1835		