

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>Mac Donald Bmo. A/c. Hq.</i>	DATE <i>24.4.41</i>	TRANSFER ORDER No. <i>397</i>
--	---------------------	-------------------------------

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>23.6.41</i>	<i>#4 T.C. #155 FTS</i>	<i>T.O. 1233</i>	<i>23 Oct 46</i>	<i>apdal mc 10 R.D. Swift Current to mc 1314</i>	
<i>12.12.42</i>	<i>Aircraft Repair 22/12</i>	<i>T.O. F-830</i>	<i>8 Oct 42</i>	<i>Wa. Assets</i>	<i>To. MC 1310</i>
<i>8.6.43</i>	<i>Stores Reserve #4TC</i>	<i>T.O. 1327</i>			
<i>23.6.</i>	<i>#4 T.C. (#2 AOS)</i>	<i>T.O. 1748</i>			
<i>1.12.43</i>	<i>A/c Repair Hdm.</i>	<i>T.O. F.1841</i>			
<i>24.2.44</i>	<i>#4 T.C. (#8 B. + G.)</i>	<i>T.O. 18584</i>			
<i>27-10-44</i>	<i>APDAL (#4TC)</i>	<i>T.O. 14863</i>			
<i>14.12.44</i>	<i>Apdal #2 A.C.</i>	<i>T.O. 47605</i>			
<i>14.12.44</i>	<i>Stores Reserve #2 A.C.</i>	<i>T.O. 17605</i>			
<i>14.2.45</i>	<i>Apdal #2 A.C.</i>	<i>T.O. 18537</i>			
APDAL #2006 REMS TO MC 15828					
DEC. SLP NO. C.P. 8-39					

REMARKS WINTER CONVERSION SET INSTALLED DURING ASSEMBLY. REF. LETTER FROM #15 T.D. 12/7/41, FILE 1021-22-1.

Hrs:-
 Since new - 744.40
 " o/h - 462.10
 U.K. Contributions
 Location: - Swift Current. #407 L.H.U.

35042/27/933

ENGINE TYPE	CHEETAH IX	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	2373/10034
BATCH No.	QUAN. IN BATCH	TP	223	LEDGER FOLIO	1200-38-9	SPECIFICATION No.	
REGISTRATION No.	MAKE & MODEL			YEAR	TYPE	MANUFACTURERS No.	
6593	*ANSON S O D			1941	T E TRAINER	W 2179	