

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
22.7.42 <sup>1</sup>	B <sup>3</sup> Crash	Central Fc. Crewlin				6.1.43	# LTC (SR)
9.6.44 <sup>2</sup>	repairs	# 6. P.D. Crews.				9.6.44	S.A. # LTC.
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

15.9.43. Modified by the addition of strengthening straps on the wing spar flanges.

14.1.44 :- Allotted #6 P.D (W.Res) for Salvage action.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT	<i>Stored Reserve, No. 196</i>		DATE	<i>26.1.42</i>	TRANSFER ORDER No.	<i>13437</i>
TRANSFERS			TRANSFERS			
	<i>Pictou</i>					
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
<i>4.6.42</i>	<i>No. 17C 318+95</i>	<i>T.O. 1108</i>				
<i>22.7.</i>	<i>Central Ice Crumlin</i>	<i>T.O. C 893</i>				
<i>6.1.43</i>	<i>Stored Reserve 1 TC 4/2</i>	<i>T.O. 47411</i>				
<i>15.9.43</i>	<i>#3 TC (T. &amp; D. Estab.)</i>	<i>T.O. 3788</i>				
<i>26.11.43</i>	<i>Stored Reserve #2 TC</i>	<i>FO 5548</i>				
<i>14.1.44</i>	<i>#6 R.D. (W. Res)</i>	<i>FO 6698</i>				
<i>1.6.44</i>	<i>Stand Reserve #1 TC</i>	<i>FO 13474</i>				
<i>15.1.45</i>	<i>STORED RESERVE No. 1 A.C.</i>	<i>T.O. 17863(C15)</i>				
<i>29.5.45</i>	<i>apdal #1 A.C.</i>	<i>T.O. 13057</i>				
	<i>AEDAL MC 4 REMU</i>	<i>TOMC15887</i>				
<i>17 Aug 46</i>	<i>Har assets</i>	<i>FO MC 12748</i>				

REMARKS

*Since new: 38.35  
 .. overhaul N.A.  
 Location: #4 R.E. m.M.*

*Purchased.*

*9422/05115  
 1561/17390*

ENGINE TYPE	JACOBS L6-MB	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	<i>TP 757</i>	LEDGER FOLIO	<i>1200-33-11</i>	SPECIFICATION No.	
REGISTRATION No.	<i>7310</i>	MAKE & MODEL	<i>PACON II</i>	YEAR	<i>1942</i>	TYPE	<i>TE TRAINER</i>
						MANUFACTURERS No.	<input checked="" type="checkbox"/>