

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
4.3.42	"C"	McDonald Bros	1500	"3 B+2, N204"	5/3	F/O J. E. Keeley	2		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

*Re Acc: - 9c collided with unoccupied 1820 and gas tank on taxi strip
Cause: Failure of starboard brake.*

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE'S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW'S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <u>16 A.R.D Jrenton</u>	DATE <u>17.10.40</u>	TRANSFER ORDER No. <u>2762</u>			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
12.11.40	# 1 T.C.	TO 5022			
19.3.41	# 2 T.C. (SE crew trainer)	TO 6551			
22.4.43	# 2 T.C. (T. Tower airplane)	TO 478			
21.3.44	Stored Reserve # 2 T.C.	T.O. 17372			
23-5-44	Apdal # 2 T.C.	T.O. 13418			
1.12.44	APDAL No. 2 AIR COMMAND	T.O. 17377 (1)			
16.2.45	War Assets Corp.	T.O. 18609			

REMARKS 22/4/43:- CONVERTED TO TARGET TOWER. U.K. CONTRIBUTION.
 Hrs:-
 SINCE NEW:- 910:00
 SINCE OVERHAUL:- nil
 LOCATION:- 304 Y

ENGINE TYPE <u>MERLIN III</u>	UNITS <u>1</u>	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH <u>TP 1</u>	LEDGER FOLIO <u>1200-38-1</u>	SPECIFICATION No.
REGISTRATION No. <u>1720</u>	MAKE & MODEL <u>BATTLE 1</u>	YEAR <u>1940</u>	TYPE <u>SE BOMBER</u>
	TARGET TOW		MANUFACTURERS No. <u>L 5020</u>