



## REMARKS:

Involved in "A" crash at No. 3 B4 G. S. Mac Donald Man.  
on 11.7.42.

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.	
		1215-8R-4		#2JC	#8 R.D. Wfg.	30.7.42	D543	
DISPOSAL PARTICULARS								
AIRFRAME	Reduced to spars & produce as per CDP 16 Chapter 21						T. O. No.	D543
ENGINE/S (QUOTE SERIAL NOS.)	" " " Merlin 8174/5143						T. O. No.	D543
AIRSCREW/S (QUOTE SERIAL NOS.)								
ACCESSORIES								
REMARKS:							EFFECTIVE DATE WRITTEN-OFF	12-8-42

## AIRCRAFT RECORD CARD

FIRST ENTRY AT			DATE	TRANSFER ORDER No.		
Mac Donald Bros, Ministry			27.11.40	5209		
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
8/2/41	#4TC					
1/3	#2TC					
25.4	Conversion Target Tow	T.O. 421				
30.7.42	Reduced to spars & produce	T.O. D543				

REMARKS 25/4/41

THIS AIRCRAFT RECEIVED AS STANDARD FROM UK - FITTED WITH GRIMMAN TOWING GEAR AT AIRCRAFT REPAIR.

ENGINE TYPE	UNITS	AIRSCREW TYPE (CODE)	REF. No.
MERLIN III			
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.
	TP 1	1200-38-1	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE
1755	BATTLE 1	1940	SE BOMBER
			MANUFACTURERS No.
			L 4940