

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1.4.42	1	C14"	Dafoc Aerod.	1435	SB 285A 11	2/4	Sgt P Blakely	2	
2.6.	2	C21"	2.2 m SW Dafoc	0730	SB 285A 25	3/6	Sgt J Adaroguz	2	Spares produce
	3								
	4								
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

*Re. acc. 2 - Connecting rod broke causing forced landing
Eng. installed 8154/2785*

REMARKS:

Involved in crash 2.6.42 near Dufour
Isle.

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
		12/15-4-5B		#2TC	#5B & 9A	11.12.42	D264

DISPOSAL PARTICULARS

AIRFRAME	Reduced to spares & produce as per CAP 16 Chap 21	T. O. No. D264
ENGINE/S (QUOTE SERIAL NOS.)		T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)		
ACCESSORIES		

REMARKS:

EFFECTIVE DATE WRITTEN-OFF

11-1-43

AIRCRAFT RECORD CARD

FIRST ENTRY AT			DATE	TRANSFER ORDER No.		
Aircraft Repair Ltd Edmonton			1/4/41	77		
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
2/5/41	#2TC, Winnipeg	T.O. 518				
11.12.42	Spares & produce	T.O. D264				

REMARKS

ENGINE TYPE	MERLIN III	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	TP 1	LEDGER FOLIO	1200-38-1	SPECIFICATION No.	
REGISTRATION No.	1306	MAKE & MODEL	BAFILE 1 (WRITE-OFF)	YEAR	1941	TYPE	S E CREW TRAINER
						MANUFACTURERS No.	L 5304