

CASPIR Aircraft Record Cards

Serial: 9834

Title: Consolidated Canso A serial:9834 Aircraft Record

Author: Royal Canadian Air Force (RCAF)

Subject: Taken on Strength: 1943-08-04. This accident involved 1 aircraft on 1943-November-08. Cnso A s/n 9834. This accident involved 12 people. Watson I, Dalgleish JB, Epstein MM, Hirtle FN, Ings RR, Lowther RF, Marsh PL, Mills EJ, Cairns WK, Morton , Redmand , Jones AH This accident had 7 fatalities. Flight Lieutenant Joseph Coates Redmond RCAF Killed in Flying Accident service no:J/5072 Canso 9834, Section Officer Irene Watson RCAFWD Killed in Flying Accident service no:V/30285 Canso 9834, Sergeant Eric John Mills RCAF Killed in Flying Accident service no:R/184018 Canso 9834, Wing Commander Ralph Royden Ings RCAF Killed in Flying Accident service no:C/27599 Canso 9834, Major Kenneth Storey Morton Army Killed in Flying Accident service no:64114 Canso 9834, Pilot Officer Robert Fleming Lowther RCAF Killed in Flying Accident service no:J/41907 Canso 9834, Warrant Officer 1st Class Mandel Max Epstein RCAF Killed in Flying Accident service no:R/104789 Canso 9834

Keywords: Canso A,9834,1943-August-04,Cairns,Dalgleish,Epstein,Hirtle,Ings,Jones,Lowther,Marsh,Mills ,Morton,Redmand,Watson

Created: 1943-08-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000357#9834>

9834

CANSO A (AMPHIBIAN) (WRITE-OFF)

1943

T E BOMBER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | | | | | | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL | DATE SERV. |
|------|----------|-------|------|------------------|------|----------------------|-------------|----------|------------|
| 1 | | | | | | | | | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

13.11.43: Allotted to 19 Sub Repair Depot (W. Res) for salvage. A crash

