

(KG 659) 994

DAKOTA III

42-9355-2

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
10 Aug 41	Spec RM-1-4	Canada air				2/Jan 50	ATC
2	(S) Arbelin						
22/3/52	necessary repairs						
3	PMI-4	Wes	4451960				
4	handy	Arac (99167)	Na 52			10 Dec 52	ATC
5	annual check	241	57254			79 Nov 56	ATC
6	bulletin						
7	15/10/54						
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
1	B	6 PD		T 210	7	Wurse			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

29 Aug 41 - 10380 (TSS) on 10380 1-7. SCR 729A, AD/APN 4, Voltage control panel, SCR 274N, BC 375B, BC 3480, SC 269G, DC 357, TR 143A, W 11F (English) RC 103A, AN/ARR.

27 Sept 47 - 10380 0999 on 10380 1-3 equipped but not fitted with low release mechanism

7 Dec 47 - a fog 5.57.1415.00, conditions did not permit test (acc data filled in with low release mechanism (low gear) considered Std Equip.

20.6.51 - period of 6 months only

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
DISPOSAL PARTICULARS							
AIRFRAME							T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)							T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)							
ACCESSORIES							
REMARKS:							EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 288D — SM-1-44 (5801) H.Q. 885 — E-289 - K.P. 99889

AIRCRAFT RECORD CARD

FIRST ENTRY AT		DATE	TRANSFER ORDER No.		
RCAP Overseas			Initial Entry		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
20 Jul 46	SR MC 10 RD - Mossbank	TO MC L2001			
18 Aug 49	MITSU (Canadian)	T.O. AMC 1228			
21 Feb 50	ATC (413 Regt)	TO - 1060			
20 Mar 50	SARL	TO 1425			
20 Apr 51	UE6RD	TO 1173			
22 Mar 52	1075U (NW) ^{Sd. NWs}	TO - 1803			
20 Dec 52	ATC (Moore Bay) ^{Sd NW1}	OTO - 1732			
7 Nov 56	MITSU ATC Co. 6	OTO 593			
1 Nov 56	ATC (Moore Bay)	OTO 593			
When of 6 allotted to contractor inventory and + SARAH in store to be done. 2/1/57					
REMARKS: 20-7-46 Recd from RCAP Overseas					
USAAF 42-93552 Recd RCAP 76-9910 2298 12/1/57 R/S 38/84					
ENGINE TYPE <i>Wasp R-130-42</i>			AIRSCREW TYPE (CODE)		REF. No. <i>350354</i>
BATCH No.		QUAN. IN BATCH	LEDGER FOLIO		SPECIFICATION No.
REGISTRATION No.		MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.
65910		Dakota	1942	ATC	42-93552

136265/562543
357171

108710242

994

DAKOTA 3SR

WASP
R1830-92

42-93552

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
20 Dec 52	ATO-1732	ATC Goose Bay			
4 Apr 57	QTO 414	11TSU AIC CR			
4 Apr 57	QTO 414	ATC Goose Bay			
30 Dec 57	184	ATC CR			
30 Dec 57	184	ATC CR			
30 Dec 57	184	ATC CR			
30 Dec 57	184	ATC CR			
30 Dec 57	184	ATC CR			
30 Dec 57	184	ATC CR			
18 Aug 60	QTO 467	11TSU AIL CR			
18 Aug 60	QTO 467	WR 6 RD			
18 Aug 60	QTO 467	ATC Star Goose Bay			
30 Oct 62	QTO 717	WR 6 RD			
6 Nov 62	ATO 753	Keyp India Air Force			
		in acc w/ Labent Government arrangements			

CAIRED: 7053 hrs 30/8/60

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
4 Apr 57	QTO 414	AIC 572859	installation of large VART13 dual ARN 64 dual 12A 67. 56B 718 is to be worked to standard search & marking to RCAF drawing 32232 are to be carried out Inverles Mods as per AMC letter to ILSU 103859-3 LCO 14.54
30 Dec 57	184	AIC L06396 7 Jan 58 572859	for double installation of and fitment of mod 6 B/24 6B/27
18 Aug 60	467	AIC 979811	for CAIR 1-11 6B/33 and AR25 against mod 6 005-35A-6A/135 installation of mod BC 453
18 Aug 60	467	WR 6 RD	for embodiment of mod 6 B/19 and 6 B/37 against Project 6 AC-321
30 Oct 62	717	WR 6 RD	Project W DNV

994

DAKOTA

3SR

RCAF REGISTRATION NUMBER

TYPE

MARK

Serial ART 13,
Serial ART 6,
magn ramp

RECORD OF TRANSFERS ✓ CGRA (N) 7/60

disc unit

DATE	AUTHORITY	ALLOTTED TO	REMARKS
4/4/57	QTO 414	AJC	
4/4/57	QTO 414	ATC - Goose Bay	24 July
30/12/57	QTO 184	AIC	replaced log 396 47 Jan 58.
30/12/57	QTO 184	ATC - Goose Bay	
18/8/60	QTO 467	AIC - CAIRI-11	Telecom Modem repair done in
18/8/60	QTO 467	WR 6 RD	done by acid MRP
18/8/60	QTO 467	ATC - New Goose Bay	at 428 Sfr Down
30/10/62	QTO 717	WR 6 RD - for project WDNV	OL 1265 6/5
			Tested with Skins

